


PRELIMINARY
NOT FOR CONSTRUCTION

This drawing was prepared under the supervision of Approver. It is not to be used for regulatory approval, permitting, or construction purposes.

FIELD INSPECTION REQUIRED

Prior to performing any bidding, new construction, and/or repairs, general contractor shall visit the site, inspect all existing conditions, and report any discrepancies to the architect.

-  WOOD SIDING WALL
-  INTERIOR WOOD STUD WALL
-  BRICK FLOOR
-  STAINED CONCRETE FLOOR
-  TILE



Scardino Play House

1203 Newning, Austin, Texas 78704

DATE	ISSUED FOR
05/16/11	Client Review
02/06/12	Client Review
02/27/12	HLC Submission

COPYRIGHT © 2011
Clayton & Little Architects
PROJECT NUMBER: Project Number

GROUND FLOOR PLAN

1 Floor Plan
1/4" = 1'-0"

A1.1

PRELIMINARY
NOT FOR CONSTRUCTION

This drawing was prepared under the supervision of Paul Clayton. It is not to be used for regulatory approval, permitting, or construction purposes.

FIELD INSPECTION REQUIRED

Prior to performing any bidding, new construction, and/or repairs, general contractor shall visit the site, inspect all existing conditions, and report any discrepancies to the architect.

Scardino Play House

1203 Newning, Austin, Texas 78704


DATE	ISSUED FOR
05/16/11	Client Review
02/06/12	Client Review
02/27/12	HLC Submission

COPYRIGHT © 2011
Clayton & Little Architects


PROJECT NUMBER: Project Number

EXTERIOR ELEVATIONS


A2.0




5 SOUTH ELEVATION
1/4" = 1'-0"




4 SOUTH ELEVATION 1
1/4" = 1'-0"



3 WEST ELEVATION
1/4" = 1'-0"



2 NORTH ELEVATION
1/4" = 1'-0"




1 EAST ELEVATION
1/4" = 1'-0"




2 Looking West




Pre-weathered Galvalume Roof




Trim - Benjamin Moore OC-122 Cotton Balls



Siding - Benjamin Moore OC-137 Sebring White



Doors and windows - Pella Iron Ore (or similar)



1 Looking Southwest

Architects
Clayton&Little

1001 East 8th Street
Austin, Texas 78702
512 477 1727

www.claytonandlittle.com

PRELIMINARY
NOT FOR CONSTRUCTION

This drawing was prepared under the supervision of Approver. It is not to be used for regulatory approval, permitting, or construction purposes.

FIELD INSPECTION REQUIRED

Prior to performing any bidding, new construction, and/or repairs, general contractor shall visit the site, inspect all existing conditions, and report any discrepancies to the architect.

Scardino Play House

1203 Newning, Austin, Texas 78704

DATE	ISSUED FOR
05/16/11	Client Review
02/06/12	Client Review
02/27/12	HLC Submission

COPYRIGHT © 2011
Clayton & Little Architects

PROJECT NUMBER: Project Number

EXTERIOR PERSPECTIVES

A2.1



West Elevation




East Elevation



South Elevation

2 Photos of existing house



1 East Elevation with existing house in context
1/8" = 1'-0"

Architects
Clayton & Little

1001 East 8th Street
Austin, Texas 78702
512 477 1727

www.claytonandlittle.com

PRELIMINARY
NOT FOR CONSTRUCTION

This drawing was prepared under the supervision of Approver. It is not to be used for regulatory approval, permitting, or construction purposes.

FIELD INSPECTION REQUIRED

Prior to performing any bidding, new construction, and/or repairs, general contractor shall visit the site, inspect all existing conditions, and report any discrepancies to the architect.

Scardino Play House

1203 Newning, Austin, Texas 78704

DATE	ISSUED FOR
05/16/11	Client Review
02/06/12	Client Review
02/27/12	HLC Submission

COPYRIGHT © 2011
Clayton & Little Architects
PROJECT NUMBER: Project Number

CONTEXT

A2.2